

APPENDIX - L

FORM "S"

(SEE RULE 88 (5))

Fire Audit Report

Year 2023

To

ST. JOSEPH'S CONVENT GIRLS'
SR. SEC. SCHOOL
1, Ahilya Bai Marg Cantt. Sadar,
JABALPUR MADHYA PRADESH

Sir,

Sub: Submission of fire audit report of ST. JOSEPH'S CONVENT GIRLS'
SR. SEC. SCHOOL , JABALPUR MADHYA PRADESH. (PRIMARY & AUDITORIUM BUILDING)

I AM **Nikhil Ranpuriya** have inspected your building / premises on **24th Nov 2023** and checked all Fire Equipment's / installations , and the entire facility.

The fire Audit of the said Building / premises of ST. JOSEPH'S CONVENT GIRLS'
SR. SEC. SCHOOL, JABALPUR MADHYA PRADESH. (PRIMARY & AUDITORIUM BUILDING HAVING
OCCUPANY GROUND + 2 FLOOR)

According to the use and character of occupancy; the campus includes building as per the NBC 2016 PART IV is belongs to GROUP B "EDUCATIONAL BUILDING".

Height of the building 10 Meter height, so it is falls under Group b (i) line item as per the NBC 2016 Part IV table no 7 that is Minimum Requirements of Fire Fighting Installations.

2. Details of fire system installed are as below:-

S.No.	Particular	Available/installed or not installed (as per requirements) (Give comments)	Comments for working of System (attach detail, if any)
1.	Access	Available	SATISFACTORY
1.	Wet Riser	Not Required as per NBC 2016 part IV table no 7	
2.	Down Comer	Not Required as per NBC 2016 part IV table no 7	
3.	Hose Reel	Available 5 nos	Working Condition
4.	Automatic Sprinkler System	Not Required as per NBC 2016 part IV table no 7	
5.	Yard Hydrant	Not Required as per NBC 2016 part IV table no 7	
6.	Underground Tank with Draw off connection	Not Required as per NBC 2016 part IV table no 7	
7.	Terrace Tank	Available (10 KL)	
8.	Fire Pump	Not Required as per NBC 2016 part IV table no 7	
9.	Terrace Pump	Available	900 LPM 1 nos – WORKING
10.	Fire Aid Fire Fighting Appliances	Available as per IS 2190	all are working

NIKHIL RANPURIYA
MP, Gov. Registered
Fire Consultant
Mob. 8962401288

11.	Pressurization System	Available	
12.	Auto detection System	Not Required as per NBC 2016 part IV table no 7	
13.	Manual Operated Electrical Fire Alarm System	Not Required as per NBC 2016 part IV table no 7	
14.	P.A. System with talk back facility	Not Required	
15.	Emergency Light	Available	Not Identified
16.	Auto D.G. Set	Not Available	
17.	Illuminated Exit Sign	Available	
18.	Means of Escape	Available	
19.	Compartmentation	Not Required	
20.	MCB/ELCB	Installed	
21.	Fireman Switch in Lift	Not Required	Lift not available
22.	Hose Boxes with Delivery hose and Branches	Not Required as per NBC 2016 part IV table no 7	Available at Ground floor
23.	Refuge Area	Not Required	
24.	Any other installation	NO	

It is Certify that the Building Fire Protection System is installed as per the NBC 2016 table no 7 and all are working condition at the time of audit.

Date: 24TH Nov 2023

Name: Nikhil Ranpuriya

Designation: Madhya Pradesh Government Authorized Fire Consultant/Lead Auditor

License No: 02/BFB/2021

NIKHIL RANPURIYA
 MP. Gov. Registered
 Fire Consultant
 Mob. 8962401266


APPENDIX - L

FORM "S"

(SEE RULE 88 (5))

Fire Audit Report

Year 2023

To

ST. JOSEPH'S CONVENT GIRLS'
SR. SEC. SCHOOL
1, Ahilya Bai Marg Cantt. Sadar,
JABALPUR MADHYA PRADESH

Sir,

Sub: Submission of fire audit report of ST. JOSEPH'S CONVENT GIRLS'
SR. SEC. SCHOOL , JABALPUR MADHYA PRADESH. (HIGH SCHOOL BUILDING)

I AM **Nikhil Ranpuriya** have inspected your building / premises on **24th Nov 2023** and checked all Fire Equipment's / installations , and the entire facility.

The fire Audit of the said Building / premises of ST. JOSEPH'S CONVENT GIRLS'
SR. SEC. SCHOOL , JABALPUR MADHYA PRADESH. (HIGH SCHOOL BUILDING HAVING
OCCUPANY GROUND + 1 FLOOR.)

According to the use and character of occupancy; the campus includes building as per the NBC 2016 PART IV is belongs to GROUP B "EDUCATIONAL BUILDING".

Height of the building 7 Meter height, so it is falls under Group b (i) line item as per the NBC 2016 Part IV table no 7 that is Minimum Requirements of Fire Fighting Installations.

2. Details of fire system installed are as below:-

S.No.	Particular	Available/installed or not installed (as per requirements) (Give comments)	Comments for working of System (attach detail, if any)
1.	Access	Available	SATISFACTORY
1.	Wet Riser	Not Required as per NBC 2016 part IV table no 7	
2.	Down Comer	Not Required as per NBC 2016 part IV table no 7	
3.	Hose Reel	Available 4 nos	Working Condition
4.	Automatic Sprinkler System	Not Required as per NBC 2016 part IV table no 7	
5.	Yard Hydrant	Not Required as per NBC 2016 part IV table no 7	
6.	Underground Tank with Draw off connection	Not Required as per NBC 2016 part IV table no 7	
7.	Terrace Tank	Available (5 KL)	
8.	Fire Pump	Not Required as per NBC 2016 part IV table no 7	
9.	Terrace Pump	Available	450 LPM 1 nos – WORKING
10.	Fire Aid Fire Fighting Appliances	Available as per IS 2190	all are working

NIKHIL RANPURIYA
MP. Gov. Registered
Fire Consultant
Mob. 8962401266

11.	Pressurization System	Available	
12.	Auto detection System	Not Required as per NBC 2016 part IV table no 7	
13.	Manual Operated Electrical Fire Alarm System	Not Required as per NBC 2016 part IV table no 7	
14.	P.A. System with talk back facility	Not Required	
15.	Emergency Light	Available	Not Identified
16.	Auto D.G. Set	Not Available	
17.	Illuminated Exit Sign	Available	
18.	Means of Escape	Available	
19.	Compartmentation	Not Required	
20.	MCB/ELCB	Installed	
21.	Fireman Switch in Lift	Not Required	Lift not available
22.	Hose Boxes with Delivery hose and Branches	Not Required as per NBC 2016 part IV table no 7	Available at Ground floor
23.	Refuge Area	Not Required	
24.	Any other installation	NO	

It is Certify that the Building Fire Protection System is installed as per the NBC 2016 table no 7 and all are working condition at the time of audit.

Date: 24TH Nov 2023

Name: Nikhil Ranpuriya

Designation: Madhya Pradesh Government Authorized Fire Consultant/Lead Auditor

License No: 02/BFB/2021

NIKHIL RANPURIYA
MP, Gov. Registered
Fire Consultant
Mob. 8962401288



APPENDIX - L

FORM "S"

(SEE RULE 88 (5))

Fire Audit Report

Year 2023

To

ST. JOSEPH'S CONVENT GIRLS'
SR. SEC. SCHOOL
1, Ahilya Bai Marg Cantt. Sadar,
JABALPUR MADHYA PRADESH

Sir,

Sub: Submission of fire audit report of ST. JOSEPH'S CONVENT GIRLS'
SR. SEC. SCHOOL , JABALPUR MADHYA PRADESH. (KG BUILDING)

I AM **Nikhil Ranpuriya** have inspected your building / premises on **24th Nov 2023** and checked all Fire Equipment's / installations , and the entire facility.

The fire Audit of the said Building / premises of ST. JOSEPH'S CONVENT GIRLS'
SR. SEC. SCHOOL, JABALPUR MADHYA PRADESH. (KG BUILDING HAVING OCCUPANY
GROUND + 2 FLOOR)

According to the use and character of occupancy; the campus includes building as per the NBC 2016 PART IV is belongs to GROUP B "EDUCATIONAL BUILDING".

Height of the building 10 Meter height, so it is falls under Group b (i) line item as per the NBC 2016 Part IV table no 7 that is Minimum Requirements of Fire Fighting Installations.

2. Details of fire system installed are as below:-

S.No.	Particular	Available/installed or not installed (as per requirements) (Give comments)	Comments for working of System (attach detail, if any)
1.	Access	Available	SATISFACTORY
1.	Wet Riser	Not Required as per NBC 2016 part IV table no 7	
2.	Down Comer	Not Required as per NBC 2016 part IV table no 7	
3.	Hose Reel	Available 3 nos	Working Condition
4.	Automatic Sprinkler System	Not Required as per NBC 2016 part IV table no 7	
5.	Yard Hydrant	Not Required as per NBC 2016 part IV table no 7	
6.	Underground Tank with Draw off connection	Not Required as per NBC 2016 part IV table no 7	
7.	Terrace Tank	Available (5 KL)	
8.	Fire Pump	Not Required as per NBC 2016 part IV table no 7	
9.	Terrace Pump	Available	450 LPM 1 nos – WORKING
10.	Fire Aid Fire Fighting Appliances	Available as per IS 2190	all are working

NIKHIL RANPURIYA
MP. Gov. Registered
Fire Consultant
Mob. 8962401266

11.	Pressurization System	Available	
12.	Auto detection System	Not Required as per NBC 2016 part IV table no 7	
13.	Manual Operated Electrical Fire Alarm System	Not Required as per NBC 2016 part IV table no 7	
14.	P.A. System with talk back facility	Not Required	
15.	Emergency Light	Available	Not Identified
16.	Auto D.G. Set	Not Available	
17.	Illuminated Exit Sign	Available	
18.	Means of Escape	Available	
19.	Compartmentation	Not Required	
20.	MCB/ELCB	Installed	
21.	Fireman Switch in Lift	Not Required	Lift not available
22.	Hose Boxes with Delivery hose and Branches	Not Required as per NBC 2016 part IV table no 7	Available at Ground floor
23.	Refuge Area	Not Required	
24.	Any other installation	NO	

It is Certify that the Building Fire Protection System is installed as per the NBC 2016 table no 7 and all are working condition at the time of audit.

Date: 24TH Nov 2023

Name: Nikhil Ranpuriya

Designation: Madhya Pradesh Government Authorized Fire Consultant/Lead Auditor

License No: 02/BFB/2021

NIKHIL RANPURIYA
MP, Gov. Registered
Fire Consultant
Mob. 8962401266

