

APPENDIX - L

FORM "S"  
(SEE RULE 88 (5))  
Fire Audit Report  
Year 2025

To

ST. JOSEPH'S CONVENT GIRLS'  
SR. SEC. SCHOOL  
1, Ahilya Bai Marg Cantt. Sadar,  
JABALPUR MADHYA PRADESH

Sir,

Sub: Submission of fire audit report of ST. JOSEPH'S CONVENT GIRLS'  
SR. SEC. SCHOOL, JABALPUR MADHYA PRADESH. (KG BUILDING)

I AM Nikhil Ranpuriya have inspected your building / premises on 23<sup>rd</sup> Nov 2025 and checked all Fire Equipment's / Installations, and the entire facility.

The fire Audit of the said Building / premises of ST. JOSEPH'S CONVENT GIRLS'  
SR. SEC. SCHOOL, JABALPUR MADHYA PRADESH. (KG BUILDING HAVING OCCUPANY  
GROUND + 2 FLOOR)

According to the use and character of occupancy; the campus includes building as per the NBC 2016 PART IV is belongs to GROUP B "EDUCATIONAL BUILDING".


Height of the building 10 Meter height, so it is falls under Group b (i) line item as per the NBC 2016 Part IV table no 7 that is Minimum Requirements of Fire Fighting Installations.


2. Details of fire system installed are as below:-

S.No.	Particular	Available/installed or not installed (as per requirements) (Give comments)	Comments for working of System (attach detail, if any)
1.	Access	Available	SATISFACTORY
1.	Wet Riser	Not Required as per NBC 2016 part IV table no 7	
2.	Down Comer	Not Required as per NBC 2016 part IV table no 7	
3.	Hose Reel	Available 3 nos	Working Condition
4.	Automatic Sprinkler System	Not Required as per NBC 2016 part IV table no 7	
5.	Yard Hydrant	Not Required as per NBC 2016 part IV table no 7	
6.	Underground Tank with Draw off connection	Not Required as per NBC 2016 part IV table no 7	
7.	Terrace Tank	Available (5 KL)	
8.	Fire Pump	Not Required as per NBC 2016 part IV table no 7	
9.	Terrace Pump	Available	450 LPM 1 nos - WORKING
10.	Fire Aid Fire Fighting Appliances	Available as per IS 2190	all are working

NIKHIL  
RANPURIYA  
A

Digitally signed by  
NIKHIL  
RANPURIYA  
Date: 2025.11.26  
23:17:08 +05'30'

  
Manager  
St Joseph's Convent Girl's  
Senior Secondary School  
Jabalpur (M.P.)

  
Principal  
St. Joseph's Convent Girls'  
Senior Secondary School  
Jabalpur

11.	Pressurization System	Available	
12.	Auto detection System	Not Required as per NBC 2016 part IV table no 7	
13.	Manual Operated Electrical Fire Alarm System	Not Required as per NBC 2016 part IV table no 7	Available at every floor – all are working
14.	P.A. System with talk back facility	Not Required	
15.	Emergency Light	Available	Not Identified
16.	Auto D.G. Set	Not Available	
17.	Illuminated Exit Sign	Available	
18.	Means of Escape	Available	
19.	Compartmentation	Not Required	
20.	MCB/ELCB	Installed	
21.	Fireman Switch in Lift	Not Required	Lift not available
22.	Hose Boxes with Delivery hose and Branches	Not Required as per NBC 2016 part IV table no 7	Available at Ground floor
23.	Refuge Area	Not Required	
24.	Any other installation	NO	

It is Certify that the Building Fire Protection System is installed as per the NBC 2016 table no 7 and all are working condition at the time of audit.

**Date:** 23<sup>rd</sup> Nov 2025

**Name:** Nikhil Ranpuriya

**Designation:** Madhya Pradesh Government Authorized Fire Consultant/Lead Auditor

**License No:** 02/BFB/2021

**NIKHIL  
RANPURIYA  
A**

Digitally signed  
by NIKHIL  
RANPURIYA  
Date: 2025.11.26  
23:17:53 +05'30'

  
Manager  
St Joseph's Convent Girl's  
Senior Secondary School  
Jabalpur (M.P.)

  
Principal  
St. Joseph's Convent Girls'  
Senior Secondary School  
Jabalpur

## FORM "S"

(SEE RULE 88 (5))

Fire Audit Report

Year 2025

To

ST. JOSEPH'S CONVENT GIRLS'  
SR. SEC. SCHOOL  
1, Ahilya Bal Marg Cantt. Sadar,  
JABALPUR MADHYA PRADESH

Sir,

Sub: Submission of fire audit report of ST. JOSEPH'S CONVENT GIRLS'  
SR. SEC. SCHOOL , JABALPUR MADHYA PRADESH. (SESQUICENTENNIAL BUILDING AND  
PRIMARY EXTENTION BUILDING)

I AM Nikhil Ranpuriya have inspected your building / premises on 23<sup>RD</sup> Nov 2025 and checked all Fire  
Equipment's / installations , and the entire facility.

The fire Audit of the said Building / premises of ST. JOSEPH'S CONVENT GIRLS'  
SR. SEC. SCHOOL, JABALPUR MADHYA PRADESH. (SESQUICENTENNIAL BUILDING AND  
PRIMARY EXTENTION BUILDING)

According to the use and character of occupancy; the campus includes building as per the NBC 2016 PART  
IV is belongs to GROUP B "EDUCATIONAL BUILDING".

Height of the building 7 Meter height, so it is falls under Group b (i) line item as per the NBC 2016 Part IV  
table no 7 that is Minimum Requirements of Fire Fighting Installations.

## 2. Details of fire system installed are as below:-

S.No.	Particular	Available/installed or not installed (as per requirements) (Give comments)	Comments for working of System (attach detail, if any)
1.	Access	Available	SATISFACTORY
1.	Wet Riser	Not Required as per NBC 2016 part IV table no 7	
2.	Down Comer	Not Required as per NBC 2016 part IV table no 7	
3.	Hose Reel	Available 4 nos	Working Condition
4.	Automatic Sprinkler System	Not Required as per NBC 2016 part IV table no 7	
5.	Yard Hydrant	Not Required as per NBC 2016 part IV table no 7	
6.	Underground Tank with Draw off connection	Not Required as per NBC 2016 part IV table no 7	
7.	Terrace Tank	Available (5 KL)	
8.	Fire Pump	Not Required as per NBC 2016 part IV table no 7	
9.	Terrace Pump	Available	450 LPM 1 nos – WORKING

NIKHIL  
RANPURIYA  
A

Digitally signed  
by NIKHIL  
RANPURIYA  
Date: 2025.11.26  
23:06:32 +05'30'

  
Manager  
St Joseph's Convent Girl's  
Senior Secondary School  
Jabalpur (M.P.)

  
Principal  
St. Joseph's Convent Girls'  
Senior Secondary School  
Jabalpur

10.	Fire Aid Fire Fighting Appliances	Available as per IS 2190	all are working
11.	Pressurization System	Available	
12.	Auto detection System	Not Required as per NBC 2016 part IV table no 7	
13.	Manual Operated Electrical Fire Alarm System	Not Required as per NBC 2016 part IV table no 7	
14.	P.A. System with talk back facility	Not Required	
15.	Emergency Light	Available	Not Identified
16.	Auto D.G. Set	Not Available	
17.	Illuminated Exit Sign	Available	
18.	Means of Escape	Available	
19.	Compartmentation	Not Required	
20.	MCB/ELCB	Installed	
21.	Fireman Switch in Lift	Not Required	Lift not available
22.	Hose Boxes with Delivery hose and Branches	Not Required as per NBC 2016 part IV table no 7	
23.	Refuge Area	Not Required	
24.	Any other installation	NO	

It is Certify that the Building Fire Protection System is installed as per the NBC 2016 table no 7 and all are working condition at the time of audit.

Date: 23<sup>rd</sup> Nov 2025

Name: Nikhil Ranpuriya

Designation: Madhya Pradesh Government Authorized Fire Consultant/Lead Auditor

License No: 02/BFB/2021

NIKHIL  
RANPURIYA  
A

Digitally signed by  
NIKHIL  
RANPURIYA  
Date: 2025.11.26  
23:07:25 +05'30'



Manager  
St Joseph's Convent Girl's  
Senior Secondary School  
Jabalpur (M.F.)



Principal  
St. Joseph's Convent Girls'  
Senior Secondary School  
Jabalpur

APPENDIX - L

FORM "S"

(SEE RULE 88 (5))

Fire Audit Report

Year 2025

To

ST. JOSEPH'S CONVENT GIRLS'  
SR. SEC. SCHOOL  
1, Ahilya Bai Marg Cantt. Sadar,  
JABALPUR MADHYA PRADESH

Sir,

Sub: Submission of fire audit report of ST. JOSEPH'S CONVENT GIRLS'  
SR. SEC. SCHOOL , JABALPUR MADHYA PRADESH. (PRIMARY & AUDITORIUM BUILDING)

I AM Nikhil Ranpuriya have inspected your building / premises on 23<sup>rd</sup> Nov 2025 and checked all Fire  
Equipment's / Installations , and the entire facility.

The fire Audit of the said Building / premises of ST. JOSEPH'S CONVENT GIRLS'  
SR. SEC. SCHOOL, JABALPUR MADHYA PRADESH. (PRIMARY & AUDITORIUM BUILDING HAVING  
OCCUPANY GROUND + 2 FLOOR)

According to the use and character of occupancy; the campus includes building as per the NBC 2016 PART  
IV is belongs to GROUP B "EDUCATIONAL BUILDING".

Height of the building 10 Meter height, so it is falls under Group b (i) line item as per the NBC 2016 Part IV  
table no 7 that is Minimum Requirements of Fire Fighting Installations.

2. Details of fire system installed are as below:-

S.No.	Particular	Available/installed or not installed (as per requirements) (Give comments)	Comments for working of System (attach detail, if any)
1.	Access	Available	SATISFACTORY
1.	Wet Riser	Not Required as per NBC 2016 part IV table no 7	
2.	Down Comer	Not Required as per NBC 2016 part IV table no 7	
3.	Hose Reel	Available 5 nos	Working Condition
4.	Automatic Sprinkler System	Not Required as per NBC 2016 part IV table no 7	
5.	Yard Hydrant	Not Required as per NBC 2016 part IV table no 7	
6.	Underground Tank with Draw off connection	Not Required as per NBC 2016 part IV table no 7	
7.	Terrace Tank	Available (10 KL)	
8.	Fire Pump	Not Required as per NBC 2016 part IV table no 7	
9.	Terrace Pump	Available	900 LPM 1 nos - WORKING
10.	Fire Aid Fire Fighting Appliances	Available as per IS 2190	all are working

NIKHIL  
RANPURIYA

Digitally signed by  
NIKHIL RANPURIYA  
Date: 2025.11.26  
23:15:17 +05'30'

  
Manager  
St Joseph's Convent Girl's  
Senior Secondary School  
Jabalpur (M.P.)

  
Principal  
St. Joseph's Convent Girls'  
Senior Secondary School  
Jabalpur

11.	Pressurization System	Available	
12.	Auto detection System	Not Required as per NBC 2016 part IV table no 7	
13.	Manual Operated Electrical Fire Alarm System	Not Required as per NBC 2016 part IV table no 7	Available at every floor – all are working
14.	P.A. System with talk back facility	Not Required	
15.	Emergency Light	Available	Not Identified
16.	Auto D.G. Set	Not Available	
17.	Illuminated Exit Sign	Available	
18.	Means of Escape	Available	
19.	Compartmentation	Not Required	
20.	MCB/ELCB	Installed	
21.	Fireman Switch in Lift	Not Required	Lift not available
22.	Hose Boxes with Delivery hose and Branches	Not Required as per NBC 2016 part IV table no 7	Available at Ground floor
23.	Refuge Area	Not Required	
24.	Any other installation	NO	

It is Certify that the Building Fire Protection System is installed as per the NBC 2016 table no 7 and all are working condition at the time of audit.

**Date: 23<sup>rd</sup> Nov 2025**

**Name: Nikhil Ranpuriya**

**Designation: Madhya Pradesh Government Authorized Fire Consultant/Lead Auditor**

**License No: 02/BFB/2021**

**NIKHIL  
RANPURIYA**

Digitally signed by  
NIKHIL RANPURIYA  
Date: 2025.11.26  
23:16:01 +05'30'



*Manager*  
St Joseph's Convent Girl's  
Senior Secondary School  
Jabalpur (M.F.)



**Principal**  
St. Joseph's Convent Girls'  
Senior Secondary School  
Jabalpur

## FORM "S"

(SEE RULE 88 (5))

Fire Audit Report

Year 2025

To

ST. JOSEPH'S CONVENT GIRLS'  
SR. SEC. SCHOOL  
1, Ahilya Bai Marg Cantt. Sadar,  
JABALPUR MADHYA PRADESH

Sir,

Sub: Submission of fire audit report of ST. JOSEPH'S CONVENT GIRLS'  
SR. SEC. SCHOOL, JABALPUR MADHYA PRADESH. (HIGH SCHOOL BUILDING)

I AM Nikhil Ranpuriya have inspected your building / premises on 23<sup>rd</sup> Nov 2025 and checked all Fire Equipment's / installations , and the entire facility.

The fire Audit of the said Building / premises of ST. JOSEPH'S CONVENT GIRLS'  
SR. SEC. SCHOOL, JABALPUR MADHYA PRADESH. (HIGH SCHOOL BUILDING HAVING  
OCCUPANY GROUND + 1 FLOOR.)

According to the use and character of occupancy; the campus includes building as per the NBC 2016 PART IV is belongs to GROUP B "EDUCATIONAL BUILDING".


Height of the building 7 Meter height, so it is falls under Group b (i) line item as per the NBC 2016 Part IV table no 7 that is Minimum Requirements of Fire Fighting Installations.

## 2. Details of fire system installed are as below:-

S.No.	Particular	Available/installed or not installed (as per requirements) (Give comments)	Comments for working of System (attach detail, if any)
1.	Access	Available	SATISFACTORY
1.	Wet Riser	Not Required as per NBC 2016 part IV table no 7	
2.	Down Comer	Not Required as per NBC 2016 part IV table no 7	
3.	Hose Reel	Available 4 nos	Working Condition
4.	Automatic Sprinkler System	Not Required as per NBC 2016 part IV table no 7	
5.	Yard Hydrant	Not Required as per NBC 2016 part IV table no 7	
6.	Underground Tank with Draw off connection	Not Required as per NBC 2016 part IV table no 7	
7.	Terrace Tank	Available (5 KL)	
8.	Fire Pump	Not Required as per NBC 2016 part IV table no 7	
9.	Terrace Pump	Available	450 LPM 1 nos – WORKING
10.	Fire Aid Fire Fighting Appliances	Available as per IS 2190	all are working

NIKHIL  
RANPURIYA

Digitally signed by  
NIKHIL RANPURIYA  
Date: 2025.11.26  
23:13:27 +05'30'

  
Manager  
St Joseph's Convent Girl's  
Senior Secondary School  
Jabalpur (M.P.)

  
Principal  
St. Joseph's Convent Girls'  
Senior Secondary School  
Jabalpur

11.	Pressurization System	Available	
12.	Auto detection System	Not Required as per NBC 2016 part IV table no 7	
13.	Manual Operated Electrical Fire Alarm System	Not Required as per NBC 2016 part IV table no 7	Available at every floor – all are working
14.	P.A. System with talk back facility	Not Required	
15.	Emergency Light	Available	Not Identified
16.	Auto D.G. Set	Not Available	
17.	Illuminated Exit Sign	Available	
18.	Means of Escape	Available	
19.	Compartmentation	Not Required	
20.	MCB/ELCB	Installed	
21.	Fireman Switch in Lift	Not Required	Lift not available
22.	Hose Boxes with Delivery hose and Branches	Not Required as per NBC 2016 part IV table no 7	Available at Ground floor
23.	Refuge Area	Not Required	
24.	Any other installation	NO	

It is Certify that the Building Fire Protection System is installed as per the NBC 2016 table no 7 and all are working condition at the time of audit.

Date: 23<sup>rd</sup> Nov 2025

Name: Nikhil Ranpuriya

Designation: Madhya Pradesh Government Authorized Fire Consultant/Lead Auditor

License No: 02/BFB/2021

NIKHIL  
RANPURI  
YA

Digitally signed  
by NIKHIL  
RANPURIYA  
Date: 2025.11.26  
23:13:55 +05'30'

  
Manager  
St Joseph's Convent Girl's  
Senior Secondary School  
Jabalpur (M.P.)

  
Principal  
St. Joseph's Convent Girls'  
Senior Secondary School  
Jabalpur